

Errata

- Page numbers after page 90 in chapter 4.5.1 are in the wrong order in the text. The next page should be page 91 and the subsequent pages should be in increasing order up to page 127, which is Appendix B, and the last page in the thesis. See the table of contents for the correct page numbers for each chapter.
- In chapter 1.4.2, the text references to Figure 7A & B in the paragraph about the last glaciation should be replaced by Figure 8A & B.

Table of Contents

Abstract.....	ii
Acknowledgments.....	iv
1 Introduction.....	1
1.1 Objectives.....	2
1.2 Geographical setting and climate.....	3
1.3 Previous events in Troms and Finnmark.....	5
1.3.1 Indre Sokkelvik and Sørkjosen.....	5
1.3.2 Lyngseidet.....	6
1.3.3 Store Lerresfjord.....	7
1.3.4 Kviby.....	7
1.4 Geological background.....	8
1.4.1 Bedrock.....	8
1.4.2 Quaternary geology.....	9
1.4.3 Landscape development.....	13
1.4.4 Mapping of sensitive clay.....	14
2 Theory and background.....	15
2.1 Clay.....	15
2.1.1 What is clay	15
2.1.2 Formation of Quick Clay.....	17
2.1.3 Typical occurrence of clay.....	16
2.1.4 Geotechnical characteristics of sensitive clay.....	17
2.1.5 Catastrophic quick clay disasters in Norway.....	20
2.2 Landslides.....	22
2.2.1 Definition of landslides.....	22
2.2.2 Why do landslides occur?.....	24
2.2.3 Consequences of landslides.....	27

2.2.4	Different types of landslides.....	28
2.2.5	Run-out areas.....	31
3	Methods.....	35
3.1	Spatial data.....	35
3.2	Fieldwork.....	35
3.3	Geotechnical testing.....	36
3.3.1	Field methods.....	36
3.3.2	Lab tests.....	37
3.4	DAN3D.....	38
3.4.1	Input data.....	41
4	Results.....	45
4.1	Description of the landslide area.....	45
4.1.1	Landslide topography.....	48
4.1.2	Description of materials.....	50
4.1.3	Detailed section and outcrop descriptions.....	52
	Section A.....	52
	Section B.....	57
	Section C.....	65
	Section D.....	69
4.1.4	Orientation data.....	76
4.2	Cross-sections.....	78
	Cross-section A-A'.....	79
	Cross-section B-B'.....	79
	Cross-section C-C'.....	80
	Cross-section D-D'.....	84
	Cross-section E-E'.....	84
4.3	Sequence of events.....	86
4.4	Previous landslide activity.....	88

4.5	Hydrometeorology.....	90
4.5.1	Snow depth and precipitation.....	90
4.5.2	Saturation of soil.....	92
4.6	Water observations.....	93
4.7	Human activity.....	97
4.7.1	Reconstruction of the E6-road.....	97
4.7.2	Digging and filling at properties.....	98
4.8	Numerical modeling.....	99
4.8.1	Model results.....	99
5	Discussion.....	104
5.1	Landscape development.....	104
5.2	Possible failure mechanisms.....	106
5.3	Modeling.....	109
5.4	Possible scenarios.....	111
5.5	Summary.....	114
6	Conclusion.....	114
	Reference list.....	117
	Appendix.....	123
	Appendix A: Geotechnical data.....	123
	Appendix B: Grid-file preparations for DAN3D.....	127